To: Stover - DNR, Bruce[bruce.stover@state.co.us]

From: Way, Steven

Sent: Mon 4/27/2015 1:47:55 PM Subject: RE: Vent Bag in Red & Bonita

Bruce,

Thanks for taking the time to look at that. My notes and subsequent report were a bit ambiguous, but we found Frontiers notes to Env Restoration. Fortunately the number I used was about 600 ft inby, just short of the 764 drift. Nothing went down the 275. (Kirstin came up with a similar distance.)

By the way, I am not going down this week. Allen and I will be there in May to discuss the plans / design for the Red and Bonita bulkhead, and I discuss our plans on the Gold King. So, if you want to join then – that's great. Otherwise, hope to see you soon.

Steve

Steven Way

Federal On-Scene Coordinator

Emergency Response Unit

US EPA - Region 8

1595 Wynkoop Street

Denver, CO 80202

Office: 303-312-6723


From: Stover - DNR, Bruce [mailto:bruce.stover@state.co.us]

Sent: Monday, April 27, 2015 7:37 AM

To: Way, Steven

Subject: Vent Bag in Red & Bonita

Steve,
Got your message Re: extent pf the vent bag installed in R&B.
I do not have the inby-end of the bag noted on my map or notes but seem to recall that it extended to just short of the "764 drift" intersection.
I recall it didn't go very far (if at all?) into the "275 drift".
I'm copying Kirstin on this as she took the pictures, and may have a photo record of where the vent bag ended.
I'm planning to be at this weeks ARSG meeting so maybe I'll see you?
Bruce K. Stover Director Inactive Mine Reclamation Program



P 303.866.3567 x <u>8146</u> | F 303.832.8106

1313 Sherman Street, Room 215, Denver, CO 80203 bruce.stover@state.co.us | http://mining.state.co.us